ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
YELAHANKA	6	Thanisandra
Street ID	**Street Name**	**Significant Landmark**
W0048	NA	R.K. Hegadenagara
Segment No.	**Total Length (m)**	
6/S-W0048/S024629	172.94	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	172.94	77.637914	13.074404	77.639468	13.074054	Mazid road	dead end

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Package no. 04 (consists of 23 works)	110000000	2017-18
Year	**Type of Work**	**Other Work Type**
2017 - 2018	Others	SSM Drain
Tender	**Work Details**	**Job No. / Work Code**
Tender		006-16-000019
Work Order No.	**Work Order Date**	**Period of Extention**
BBMP/EE/BTP/WO/62/2018-19	24/07/2018	
Defect Liability Period From	**Defect Liability Period To**	**Multiple road involved with the same Job No/ Work Code #**
24/07/2018	24/07/2021	No

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
M.S.VENKATESH		0.00
Phone No.	**E-Mail ID**	
9886066040		

Scanned by CamScanner

Field Inspection Details

Number of Trees	Any Other Information	Name
0		daramsingh

Date of Inspection	Remarks
15/05/2019	

Category	Image	Photo Remark
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	Sri.R.L.Parameshwaraiah	22/05/2019	14/06/2019	Approved
SE	Basavaraj R Kabade	16/05/2019	14/06/2019	forwarded
EE	Mohandas H.T	15/05/2019	14/06/2019	completed
AEE	Sridhar B.S	15/05/2019	14/06/2019	verified
AE	Daramsingh	15/05/2019	14/06/2019	Mobile verification is done
AE	Daramsingh	15/05/2019	14/06/2019	Forwarded

Scanned by CamScanner